

00862.002746.1



COFC

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

MITSUYA SATO

→ Appln. No.: 09/940,461

Filed: August 29, 2001

For: EXPOSURE APPARATUS AND  
METHOD, DEVICE  
MANUFACTURING METHOD,  
AND DISCHARGE LAMP

)  
:  
Examiner: Peter B. Kim  
)  
:  
Group Art Unit: 2851  
)  
:  
Patent No.: 6,771,353 B2  
)  
:  
Issued: August 3, 2004  
)  
:  
October 8, 2004  
:

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Attention: **CERTIFICATE OF CORRECTIONS BRANCH**

**Certificate**  
**OCT 1 5 2004**  
**of Correction**

REQUEST FOR A CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency

10/12/2004 CNGUYEN 00000107 6771353

01 FC:1811

100.00 DP

OCT 1 8 2004

should be charged and any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Steven E. Warner", written over a horizontal line.

Attorney for Patentees  
Steven E. Warner  
Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2200

SEW/klm

DC\_MAIN 178541v1

00862.002746.1

PATENT



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

MITSUYA SATO

Appln. No.: 09/940,461

Filed: August 29, 2001

For: EXPOSURE APPARATUS AND  
METHOD, DEVICE  
MANUFACTURING METHOD,  
AND DISCHARGE LAMP

)  
:  
Examiner: Peter B. Kim  
)  
:  
Group Art Unit: 2851  
)  
:  
Patent No.: 6,771,353 B2  
)  
:  
Issued: August 3, 2004  
)  
:  
October 8, 2004  
:

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

**Attention: CERTIFICATE OF CORRECTIONS BRANCH**

REQUEST FOR A CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323

Sir:

Patentees request that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.


Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency

OCT 18 2004

should be charged and any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' undersigned attorney may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

  
Attorney for Patentees  
Steven E. Warner  
Registration No. 33,326

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2200

SEW/klm

DC\_MAIN 178541v1

OCT 18 2004

**Staple  
Here  
Only!**

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,771,353 B2

DATED : August 3, 2004

INVENTOR(S) MITSUYA SATO

Page 1 of 2

COLUMN 1:

Line 20, "i line-light" should read --i line light--.

COLUMN 5:

Line 11, "light," should read --light.--.

Line 24, "point." should read --unit.--

COLUMN 7:

Line 16, "fly eye's" should read --fly's eye--.

Line 24, "of" should read --of the--.

MAILING ADDRESS OF SENDER:

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,771,353 B2

No. of add'l. copies  
@ 30¢ per page



**OCT 18 2004**

**Staple  
Here  
Only!**

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,771,353

DATED : August 3, 2004

INVENTOR(S) MITSUYA SATO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 2, "ship" should read --chip--.

COLUMN 10:

Line 19, "apparatuses" should read --apparatus--.

Line 24, "senor," should read --sensor,--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,771,353 B2

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

FORM PTO 1050 (REV. 3.82)



OCT 18 2004

**Staple  
Here  
Only!**

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,771,353 B2

DATED : August 3, 2004

INVENTOR(S): MITSUYA SATO

Page 1 of 2

COLUMN 1:

Line 20, "i line-light" should read --i line light--.

COLUMN 5:

Line 11, "light," should read --light.--.

Line 24, "point." should read --unit.--

COLUMN 7:

Line 16, "fly eye's" should read --fly's eye--.

Line 24, "of" should read --of the--.

MAILING ADDRESS OF SENDER:

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

FORM PTO 1050 (REV. 3.82)

PATENT NO. 6,771,353 B2

No. of add'l. copies  
@ 30¢ per page



OCT 18 2004

**Staple  
Here  
Only!**

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,771,353

DATED : August 3, 2004

INVENTOR(S): MITSUYA SATO

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 2, "ship" should read --chip--.

COLUMN 10:

Line 19, "apparatuses" should read --apparatus--.

Line 24, "senor," should read --sensor,--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,771,353 B2

**FITZPATRICK, CELLA, HARPER & SCINTO**  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

No. of add'l. copies  
@ 30¢ per page

FORM PTO 1050 (REV. 3.82)



OCT 18 2004